

AFTER SALES SERVICE Service Instruction Sheet

Part Number: 4000477327;



M18SISH Software update

Updated on: 12/122024

The latest **PC-Software** can be downloaded at:

https://milwaukee-downloads.s3.eu-west-2.amazonaws.com/MTCam_PC_SW_v1.16%20%283%29.msi

The latest software can be downloaded here:

SMART HUB UPDATE 3.0.0.75:

https://milwaukee-downloads.s3.eu-west-2.amazonaws.com/MTCam_hub_RK3568_3_0_0_75.zip

Download, unzip the file, and copy it to a USB-Drive.

Step 1

Open USB Cage:



Step 2

Enter USB-Drive into USB-A port:



¹ No communication outside TTI SBU's and EMEA

² Importers, distributors and service providers in a country (where there is no TTI SBU management)

³ SBU's

⁴ Network of customers who sell our tools in a country, managed by TTI SBU

⁵ Network of service center managed by a SBU




Step 3

Navigate to Settings:



Step 4

Go to System Update:



Step 5


Go to Control Hub:





Step 6

Go to Update File:



Step 7

Confirm Software Update:



Step 8

Smart Hub is updating
(takes 2-5 minutes)





Step 9

Smart Hub Restarts after Update is Complete

